

SAFEWARE SERVICE RATES

Onsite Service may include travel and accomodation charges

	Price	Discount	US Com Price	UOM
Regulator Flow Testing: Scott, MSA, Survivair, and Draeger	65.00	10%	58.50	EA
Regulator Flow Testing: Interspiro	95.00	10%	85.50	EA
*Includes Batteries as needed				
Hydrostatic testing cylinders up to 4500 psi	27.00	10%	24.30	EA
Includes: Hydro, Devalving and O-ring replacement (excluding fill)				
Cylinder Refill up to 4500 psi	8.00	10%	7.20	EA
*Hazmat shipping fee's apply for refilled cylinders				
Portable Gas Detection: Preventative Maintenance and Evaluation	170.00	10%	153.00	EA
*Price based on standard 4 gas mix and excluding parts				
Respirator fit test:				
Per mask QUALITATIVE MANUAL FIT TEST	25.00	10%	22.50	EA
Quantitative fit test:				
Per mask QUANTITATIVE COMPUTER FIT	45.00	10%	40.50	EA
Level A Suit Pressure Test and Certification	105.00	10%	94.50	EA
(NOTE: Suits must be decontaminated with letter of decon certification attached to each suit before work can be performed)				
Mask Cleaning: Cleaning	50.00	10%	45.00	EA
SCBA Cleaning: Mask, Tank, Case and Cylinder refill	75.00	10%	67.50	EA
(Replacement parts not included)				
Fire Hose Testing: Fire Hose test Price per foot	0.85	10%	0.77	EA
Gas Detection Labor Charge: Per Hour	95.00	10%	85.50	EA
Evaluation Charge: Should Customer refuse repair	75.00	10%	67.50	EA
*Fee is waived if customer replaces equipment through Safeware				
Rush Charge, 24 Hour turnaround	100.00	10%	90.00	EA
Completion of rush repair is dependent on parts and availability				
Pick up or Delivery: Per Acurance	150.00	10%	135.00	EA
*Availble up to 60 mile radius from service center				
On-site Fee: This is an on-site charge Available within 60 Mile radius of Service Center	650.00	10%	585.00	EA

ADDITION SERVICES

			Price	Discount	US Com Price	UOM
DBI	DBI 3400115 SRL 50ft	Recertification Service	540.00	10%	486.00	EA
DBI	DBI 3400407 SRL 130ft	Recertification Service	821.00	10%	738.90	EA
DBI	DBI 3504450 SRL ULTRLOK 50ft	Recertification Service	286.00	10%	257.40	EA
DBI	DBI 3000150 SRL 39ft	Recertification Service	340.00	10%	306.00	EA
Miller	MightyLite RL20, RLS30 SRLs	Recertification Service	253.00	10%	227.70	EA
Miller	MightyLite RL30, 50, 65 SRLs	Recertification Service	299.00	10%	269.10	EA
Miller	MightyLite RL100, 130 SRLs	Recertification Service	439.00	10%	395.10	EA
Miller	M52 & 52 SRL's w/retrieval	Recertification Service	450.00	10%	405.00	EA
Miller	Manhandler 8440, 8441, 8442	Recertification Service	180.00	10%	162.00	EA
MSA	Dynalock 20'	Recertification Service	524.00	10%	471.60	EA
TSI	Port Count 8020	Calibration	875.00	10%	787.50	EA
Smiths Detection	APD2000	Calibration & Clean	605.00	10%	544.50	EA
Elwood Safety	Electrical Gloves Testing	Dielectric testing inspection and labeling.	21.95	10%	19.76	EA
Elwood Safety	Electrical Blanket Testing	Dielectric testing inspection and labeling.	23.00	10%	20.70	EA
Elwood Safety	Electrical Sleeves Testing	Dielectric testing inspection and labeling.	23.00	10%	20.70	EA
Elwood Safety	Electrical Hot Sticks	Dielectric testing inspection and labeling.	6.00	10%	5.40	FT
Drager	Drager CMS Unit – Gas detection analyser		149.00	10%	134.10	EA
Pro Engine	AP2C – Chemical Contamination Control Device		693.00	10%	623.70	EA

FIRE RELATED SERVICES	Price	Discount	US Com Price	UOM
Not available in all areas				
<u>Portable Fire Extinguishers</u>				
Flat rate Minimum Service Charge for Individual sites with 1 to 8 fire extinguishers	45.00	10%	40.50	EA
Annual Fire Extinguisher inspection per NFPA #10 standards	5.50	10%	4.95	EA
<u>Hydrostatic Testing Per Extinguisher</u>				
Dry Chemical/H2O/K-Class (Low Pressure)	12.00	10%	10.80	EA
CO2, SCBA, (High Pressure)	16.00	10%	14.40	EA
6 year Maintenance for dry chemical extinguishers	10.00	10%	9.00	EA
<u>Recharge Fire Extinguishers (not including repair parts)</u>				
Dry Chemical ABC/BC				
Dry Chemical ABC/BC 20lb	25.00	10%	22.50	EA
Dry Chemical ABC/BC 10lb	20.00	10%	18.00	EA
Dry Chemical ABC/BC 5lb	16.00	10%	14.40	EA
Dry Chemical ABC/BC 2-1/2lb	14.00	10%	12.60	EA
CO2 20lb	16.00	10%	14.40	EA
CO2 15lb	15.00	10%	13.50	EA
CO2 10lb	12.00	10%	10.80	EA
CO2 5lb	10.00	10%	9.00	EA
H2O	10.00	10%	9.00	EA
Class K (6 Liter)	85.00	10%	76.50	EA
<u>Kitchen Hood Fire Suppression Service</u>				
Semi-Annual test and inspection per NFPA Standards	75.00	10%	67.50	EA
\$15.00 each for each extra cylinder per system.				
Fusible link detectors changed semi-annually per NFPA Standards	10.00	10%	9.00	EA
<u>Fire Alarm System test and inspection per NFPA Standards</u>				
Control Panel	150.00	10%	135.00	EA
Individual Devices (pull station, horn strobe, detector etc)	10.00	10%	9.00	EA

DBI	DBI 3400115 SRL 50ft
DBI	DBI 3400407 SRL 130ft
DBI	DBI 3504450 SRL ULTRLOK 50ft
DBI	DBI 3000150 SRL 39ft
Miller	MightyLite RL20, RLS30 SRLs
Miller	MightyLite RL30, 50, 65 SRLs
Miller	MightyLite RL100, 130 SRLs
Miller	M52 & 52 SRL's w/retrieval
Miller	Manhandler 8440, 8441, 8442
MSA	Dynalock 20'
TSI	Port Count 8020
Smiths Detection	APD2000
Elwood Safety	Electrical Gloves Testing
Elwood Safety	Electrical Blanket Testing
Elwood Safety	Electrical Sleeves Testing
Elwood Safety	Electrical Hot Sticks
Drager	Drager CMS Unit – Gas detection analyser
Pro Engine	AP2C – Chemical Contamination Control Device

	Our Cost	List Cost
Recertification Service	\$402.00	\$540.00
Recertification Service	\$615.75	\$821.00
Recertification Service	\$214.50	\$286.00
Recertification Service	\$255.00	\$340.00
Recertification Service	\$209.00	\$253.00
Recertification Service	\$242.00	\$299.00
Recertification Service	\$338.00	\$439.00
Recertification Service	\$344.00	\$450.00
Recertification Service	\$149.00	\$180.00
Recertification Service	\$393.00	\$524.00
Calibration	\$655.00	\$875.00
Calibration & Clean	\$445.00	\$605.00
Dielectric testing inspection and labeling.	\$13.50	\$21.95
Dielectric testing inspection and labeling.	\$15.00	\$23.00
Dielectric testing inspection and labeling.	\$15.00	\$23.00
Dielectric testing inspection and labeling.	\$4.00 per foot	\$6.00 per foot
	\$93.75	\$149.00
	\$453.60	\$693.00

<u>Portable Fire Extinguishers</u>	Price
Flat rate Minimum Service Charge for Individual sites with 1 to 8 fire extinguishers	45.00
Annual Fire Extinguisher inspection per NFPA #10 standards	5.50
<u>Hydrostatic Testing Per Extinguisher</u>	
Dry Chemical/H2O/K-Class (Low Pressure)	12.00
CO2, SCBA, (High Pressure)	16.00
6 year Maintenance for dry chemical extinguishers	10.00
<u>Recharge Fire Extinguishers (not including repair parts)</u>	
Dry Chemical ABC/BC	
Dry Chemical ABC/BC 20lb	25.00
Dry Chemical ABC/BC 10lb	20.00
Dry Chemical ABC/BC 5lb	16.00
Dry Chemical ABC/BC 2-1/2lb	14.00
CO2 20lb	16.00
CO2 15lb	15.00
CO2 10lb	12.00
CO2 5lb	10.00
H2O	10.00
Class K (6 Liter)	85.00
<u>Kitchen Hood Fire Suppression Service</u>	
Semi-Annual test and inspection per NFPA Standards	75.00
\$15.00 each for each extra cylinder per system.	
Fusible link detectors changed semi-annually per NFPA Standards	10.00
<u>Fire Alarm System test and inspection per NFPA Standards</u>	
Control Panel	150.00
Individual Devices (pull station, horn strobe, detector etc)	10.00